



# PRODUCTS CHEMICAL

## MOP VAC STRIPPER

### No Rinse • No Scrub Liquifying Stripper

*Mop Vac Stripper* is a super aggressive, Phase III stripper. A 55% active speed stripper that easily cuts through multi-layers of burnished floor finish. A “true” no rinse stripper. Does not contain butyl, potassium hydroxide or sodium hydroxide, yet is the fastest working liquefier on the market. Low foaming. No scrub or rinse. Floor finish removal is accomplished without the use of floor machine, stripping pads and excessive costly labor. This product is a must for all professional floor care systems.

For the rapid removal of all floor finishes and waxes from resilient flooring including vinyl, vinyl asbestos, vinyl composition, asphalt, linoleum and rubber tiles. Also ideal for finished non-resilient such as terrazzo, marble, ceramic, quarry tile, concrete and poured epoxy flooring. Although excellent for any type of equipment, greatest savings are realized when using automatic scrubbing equipment.

#### Benefits

- Super aggressive. Low foam. Can be used through automatic scrubbers.
- Removes floor finish without a floor machine, stripping pads, or excessive rinsing.
- Saves on costly labor.
- Penetrates and liquefies old floor wax.
- Evaporates quickly.
- New coats of finish bond perfectly with floor surface.

#### Features

- Eliminates costly equipment
- Leaves no residue alkali film
- Easy to use.
- Mop on. Wet vac off.
- Contains no potassium or sodium hydroxide. Safe for personnel and floors.
- High use dilution for greater economy.



## The Product

*Mop Vac Stripper* is a no-rinse, super aggressive floor finish stripper. Its non-butyl formula has unusual penetrating and liquefying properties for removing finished from floors quickly. When used as directed, this stripper will totally re-liquefy all old floor finish, including finishes that have been burnished "hard". Floor finish removal is accomplished without the use of floor machines, stripping pads and excessive costly labor.

## Recommended Use Directions

Mix at the ratio of 1:4 using hot water, (1 gallon of stripper to 4 gallons of water) Apply liberally, but uniformly, to floor with mop or autoscrubber. Allow stripper to remain 5-7 minutes and remop. Keep area wet. Do not allow solution to dry on floor. Pick up solution using a wet vac, clean mop, or an automatic scrubber. Allow floor to dry completely.

## Product Characteristics

Packaged . . . . .	Drums, 5 gallon pails, 4x1 gallon cases
Appearance . . . . .	Yellow liquid
Odor . . . . .	Characteristic
pH Range . . . . .	12.0 concentrate
Flash Point . . . . .	Non. Non flammable
Water Solubility . . . . .	Complete
Finish Removal . . . . .	Excellent
Free Rinsing . . . . .	Yes
Low Foaming . . . . .	Yes

Shelf Life . . . . 1 year minimum in original unopened container.

## Storage and Handling

Warning: Irritant. Causes skin and eye irritation. Do not take internally. Harmful if swallowed. Avoid contact with eyes, skin and clothing. Store in a cool dry place. Wash hands thoroughly with warm, soapy water after handling. For professional use only.

Refer to product label and SDS for additional information

8/07

@ 2007 Products Chemical Company All rights reserved